

**Parts needed to mount the PAC-ALU extrusion**



Extrusion (A)



End caps (B)



Cover (C)



LED strip (D)


**Tools needed for mounting:**

- mounting glue

**WARNING!** All LED strips should be connected to a 12 V or 24 V power supply.

**IMPORTANT:** The mounting instructions present the basic form of assembly. More methods and related accessories can be found at [www.KlusDesign.com](http://www.KlusDesign.com)

**1.** Mount the LED strip (D), insert the cover (C), and then insert the end cap (B). Feed the power cable.



**2.** Apply glue to the mounting surface. Connect power and mount the extrusion.

