

### Parts needed to mount the PIKO extrusion



Extrusion (A)



End caps (B)



Cover (C)




LED strip (D)

**WARNING!** All LED strips should be connected to a 12 V or 24 V power supply.

**IMPORTANT:** The mounting instructions present the basic form of assembly.  
More methods and related accessories can be found at [klusdesign.com](http://klusdesign.com)

**1.** Mount the LED strip (D), insert the cover (C), and then insert the end cap (B). Run the cable to the power source.



**2.** Apply double-sided tape to the extrusion (A), and attach the extrusion to the surface. Connect power.

