

Parts needed to mount the MICRO-ALU profile



Mounting bracket (A)



Extrusion (B)



LED strip (C)



Cover (D)



End cap (E)


Tools needed for mounting:

- drill
- screwdriver


WARNING! All LED strips should be connected to a 12 V or 24 V power supply.

IMPORTANT: The mounting instructions present the basic form of assembly. More methods and related accessories can be found at www.KlusDesign.com

1. Feed the power cable. Attach the mounting bracket (A) to the surface with bolts.



2. Install the LED strip (C) in the extrusion (B), insert the cover (D) and the end caps (E).



3. Connect power to the LED strip and mount the extrusion (B) in the mounting bracket.

