


1. Attach the mounting bracket to the surface with screws.

2. Insert the extrusion in the mounting bracket.



**NOTE!** A list of products corresponding with the selected accessories is available at [klusdesign.com](http://klusdesign.com).